




Automatic Dimming Inside Mirror



NOTE: Wires that look like this  are part of the Honda Accessory harness installed between factory harness connectors/components sockets.


Automatic Dimming Inside Mirror

Automatic Dimming Inside Mirror In-line Fuse (+B)




1. PNK (+B HAC OP)
2. WHT (+B HAC OP(2A))

Automatic Dimming Inside Mirror In-line Fuse (IG1)




1. BRN (IG1 METER)
2. GRY (IG1 HAC(2A))

Automatic Dimming Inside Mirror



1. WHT (+B HAC OP(2A))
2. PUR (ILLUMI+)
3. —
4. —
5. —
6. LT GRN (BACK LT)
7. BLK (GND)
8. GRY (IG1 HAC(2A))

Under-dash Fuse/Relay Box Connector J



1. BRN (IG1 METER)
2. RED (ACC)
3. PUR (ILLUMI+)
4. LT GRN (BACK LT)
5. —
6. PNK (+B HAC OP)